

It's what we can do, at this moment now.Vol.5

Support of handling non-woven fabric.

Haven't you handled non-woven fabric for protective gown during the pandemic?

There was a case of difficulties of setting them to the machine. Since the thickness of the non-woven fabric, 2,500m roll and 1,600m roll and the diameter of them are over 80cm, and the weight are over 80kg.

(There was a case of difficulties of setting them to the machine.)

As a solution, we are providing the service of rewinding for a smaller roll at Mikuni and Iwaki production base.If you have the same problem, please let us know.

